


1983 Borah Peak Earthquake



Doublespring Pass Road





Idaho

Mount Borah

Mount Borah

ISU Field Station (Right Here)

1983 Earthquake Epicenter

93

© 2005 TeleAtlas
Image © 2005 EarthSat


© 2005 Google

The direction of movement along the fault was predominantly vertical, but the broken drainage ditch shows that some lateral movement also occurred.




Photo courtesy of Walter J. Arabasz, University of Utah


Right Lateral / Right-Stepping




Left Lateral / Right-Stepping




Right Lateral / Left-Stepping



Left Lateral / Left-Stepping





Combination strike-slip/
reverse motion




Combination strike-slip/
normal motion

Fault Plane Solutions


(Focal Mechanism Solutions, Beach ball Diagrams)




Two strike-slip fault
plane solutions





Two reverse fault
plane solutions



Two normal fault
plane solutions









Thompson, et al., 1967

Dip slip and oblique slip on crooked normal fault



Doublespring Pass Rd.





Detail Area



Idaho

Lateral spreading caused by soil liquefaction



Photo courtesy of Earle S. Eppich, Reaveley Engineers & Assoc., Salt Lake City, UT



Photo courtesy of Ogden Standard Examiner